


LIVE WORK

Trainers and HV LIVE LINE Work Selection Method.











EEA.CO.NZ



Gavin Paget May 2021 Trainer Forum

1

BACKGROUND

Powerco HV Live Line Working Group

We have been engaged with our Live Line (LL) service providers and the EEA over the last 3 years to:

- Standardise an approach to planning work that allows the use of LL techniques to complete tasks on the HV Network.
- Establish a Work Method Selection Guide that considers the risks of completing the work live vs. isolated to reduce the risk to ALARP.
- Reference a suite of 'standard' guidelines that can be used by the service providers to base their procedures on to ensure consistency regardless of the contactor in line with EEA Live work HV guides.
- Use an Asset Exclusion List that defines the assets what we deem too complex to work on in the energised state.
- Always use a Work Method Selection Guideline and document the outcome
- Ensure ECP46 +Practise notes compliance.



EEA.CO.NZ



Powerco Work Method Selection Guide Form

A document intended to supplement the decision-making process for determining the preferred work methodology (live or isolated) on our HV overhead network.

Powerco needs to;

- Understand the "risks" associated with HV LL work.
- Identify possible work methodologies in the design, planning and delivery aspects of the project life cycle.
- Know when LL is being considered as a work method to complete a task.

Service providers and Trainers need to;

- Understand the "risks" associated with HV LL work.
- Have a structured decision making process that evaluates work methods against a set list of risk based criteria to determine the most suitable method to undertake work on an HV overhead Line
- Communicate to Powerco when a LL job is being considered as a work method to complete a task.

EEA.CO.NZ



3

STANDARD GUIDELINES

A suite of documents published in BMS & CWM that provides step-by-step guidance on how to complete certain tasks using LL methods. Established in conjunction with our service providers and the EEA who have also published their own version of some of the documents.

To date, Powerco has published into the BMS;

- · 37 guidelines
- Work Method Selection guide \$2505271
- Work Method Selection Form 250F002
- · A Live Line Works Principles overarching document
- An Asset Exclusions List

Service providers have their own Work Selection Methods and LL manuals. The relevant procedures must align with the Powerco guidelines for the same work. Work Method Selection must align with EEA guide and Powerco Selection methods.



EEA.CO.NZ



ASSET EXCLUSION LIST



A list of assets with known defects or issues that Powerco deems too risky to work on in the energised state due to the risk they pose to the workers.

The initial list has been revised and currently there are 12 items on the list that will be reviewed annually:

- Surge / lightning arrestors
- Conductors on an angle greater than 30°
- Copper or Aluminum wire less than 25mm² or No.8 wire
- Replacing in-line tension joints
- Replacing Twisty or Fargo joints
- Cable termination pot-heads
- Damaged or cracked insulators
- Two-piece 33kV insulators
- Zone substations
- Voltage Regulators
- Capacitors
- Single Wire Earth Return (SWER) lines

EEA.CO.NZ

POWERCO

5


EEA Assessment Of Work Methods To Undertake HV

OH Line WORK

 Trainers should complete a work selection method when training HV tasks on a network.

Always follow the Three Risk criteria -

- Risk 1 _ Is it not reasonably practical in all circumstances for the line to be de-energized.
- Risk 2 _ Is it reasonable in all circumstances for the employee to be working on a live uninsulated conductor.
- Risk 3_ Are there limitations on the scope of work that can be undertaken, specifically safety justifications not to proceed.
- Single Wire Earth Return (SWER) lines



EEA.CO.NZ



ECP46 and Practise Notes Compliance

Request for information letters sent to our four approved LL service providers Trainers (Downer, Electrix, Northpower and Scanpower) seeking confirmation of compliance with ECP46 in areas that are not observable or auditable on site.

Service providers confirmation that they believe their processes and systems comply with the requirements of ECP46 regarding:

- · Staff selection, training and refreshers
- · Health monitoring of workers
- Procurement and storage of LL equipment
- · Establishment and proving of procedures
- Record keeping
- Auditing




EEA.CO.NZ




7


Powerco HV Live Work Selection Guide





EEA.CO.NZ












EEA Work Method Selection Electricity Engineers' Association Assessment of work Method to undertake High Voltage overhead Live Line Work Guide Copyright i Status of Examples and Case Studies Preface 1 Objectives and Scope 2 Legislation 3 References Definitions 3.1 4 Work method risk assessment 5 Overview 5 4.2 Approach5 4.3 Planning 6 Risk Assessment – Criteria 1 6 Risk Assessment – Criteria 2 7 Risk Assessment – Criteria 3 8 4.4 4.5 4.7 Assessment 10 4.8 Pre-work Assessment 10 5 Flowchart Example Criteria 11 Appendix A Customers **EEA.CO.NZ** POWERCO

13



EEA Work Method Selection

Assessment of work Method to undertake High Voltage overhead Live Line Work Guide Some useful EEA publications

Electricity Engineers' Association

"EEA Knowledge Centre"

- May 2017 EEA ECP 46 Industry practice note (supplement to NZECP 46)
 Nov 2019 EEA HV Voltage Live Work Model Procedures for Glove and Barrier work, (11 procedures)
- Sep 2016 EEA Guide for the Assessment of Work methods to Undertake High Voltage Overhead Line work
- Dec 2019 EEA Live Line Work restart Industry Practice Note
 July 2020 EEA High Voltage Live Work Auditing and Inspection Guide.



EEA.CO.NZ



15

QUESTIONS?



EEA.CO.NZ

